

2004 - 2009 Cadillac XLR: Service Bulletin: Red LED and B2455 After Performing Canada Upgrade Bulletin 15-08-44-001

#PIC6140B: Red LED and B2455 After Performing Canada Upgrade Bulletin 15-08-44-001 - (Dec 21, 2015)

Subject:	Red LED and B2455 After Performing Canada Upgrade Bulletin 15-08-44-001
Models:	2005-2009 Buick Allure 2004 Buick Century 2005-2009 Buick LaCrosse 2000-2005 Buick LeSabre 2004-2007 Buick Rainier 2004 Buick Regal 2003-2007 Buick Rendezvous 2005-2007 Buick Terraza 2003-2007 Cadillac CTS 2002-2005 Cadillac Deville 2003-2006 Cadillac Escalade 2002-2004 Cadillac Seville 2004-2006 Cadillac SRX 2004-2011 Cadillac STS 2004 - 2009 Cadillac XLR 2003-2006 Chevrolet Avalanche 2005-2010 Chevrolet Cobalt 2004-2012 Chevrolet Colorado 2005-2013 Chevrolet Corvette 2005-2006 Chevrolet Equinox 2004-2005 Chevrolet Express 2006-2011 Chevrolet HHR 2001-2005 Chevrolet Impala 2004-2012 Chevrolet Malibu 2002-2005 Chevrolet Monte Carlo 2003-2007 Chevrolet Silverado 2003-2006 Chevrolet Suburban 2003-2006 Chevrolet Tahoe 2009-2009 Chevrolet Trailblazer 2005-2009 Chevrolet Uplander 2003-2005 Chevrolet Venture

2004-2012 GMC Canyon
2002-2009 GMC Envoy
2003-2005 GMC Savana
2003-2007 GMC Sierra
2003-2006 GMC Yukon/Yukon XL
2003-2007 Hummer H2
2006-2011 Hummer H3
2001-2003 Oldsmobile Aurora
2002-2004 Oldsmobile Bravado
2003-2004 Oldsmobile Silhouette
2003-2005 Pontiac Aztec
2000-2005 Pontiac Bonneville
2007-2010 Pontiac G5
2005-2010 Pontiac G6
2004-2008 Pontiac Grand Prix
2003-2009 Pontiac Montana
2005-2006 Pontiac Pursuit
2006-2010 Pontiac Solstice
2004-2005 Pontiac Sunfire
2006 Pontiac Torrent
2005-2008 Pontiac Vibe
2008-2009 Saturn Astra
2007-2010 Saturn Aura
2004-2007 Saturn ION
2003-2004 Saturn L-Series
2005-2007 Saturn Relay
2007-2010 Saturn Sky
2003-2007 Saturn Vue

This PI has been updated to include an updated Warranty Information. Please disregard PIC6140A.

Condition/Concern

A dealer or customer may notice a red LED and DTC B2455 setting current in the VCIM after performing Canada upgrade bulletin 15-08-44-001.

When placing calls or connecting to OnStar, the person on the other end is able to hear the caller clearly.

Recommendation/Instructions

3. Tape the bare wires individually to prevent them from shorting. Then tape the harness back up.

Online URL: <https://xlr-net.com/knowledgebase/article.php?id=7>