

# 2006 - 2009 Cadillac XLR and XLR-V: Service Bulletin: #PIP4021D: High Pitch Whine or Buzz Noise Heard From Under The Vehicle - (Feb 21, 2019)

## #PIP4021D: High Pitch Whine or Buzz Noise Heard From Under The Vehicle - (Feb 21, 2019)

**Subject:** High Pitch Whine or Buzz Noise Heard From Under The Vehicle

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	ATS	2013-2015		All	All	All	MYA
Cadillac	CTS	2008-2015		All	All	All	MYA, MYB, MYD
Cadillac	Escalade Models	2007-2017		All	All	All	MYC
Cadillac	SRX	2007-2009		All	All	All	MYB
Cadillac	STS	2006-2011		All	All	All	MYB, MYC
Cadillac	XLR Models	2006-2009		All	All	All	MYC
Chevrolet	Avalanche	2009-2013		All	All	All	MYC

Chevrolet	Camaro	2010-2015	All	All	All	MYB, MYC, MYD
Chevrolet	Colorado	2015-2019	All	All	All	MYB
Chevrolet	Corvette	2006-2014	All	All	All	MYC
Chevrolet	Express	2010-2019	All	All	All	MYD
Chevrolet	Silverado	2007-2019	All	All	All	MYC, MYD
Chevrolet	Suburban	2009-2019	All	All	All	MYC, MYD
Chevrolet	Tahoe	2009-2019	All	All	All	MYC, MYD
GMC	Canyon	2015-2019	All	All	All	MYB
GMC	Savana	2010-2019	All	All	All	MYD
GMC	Sierra	2009-2019	All	All	All	MYC, MYD
GMC	Yukon Models	2007-2019	All	All	All	MYC
Hummer	H2	2008-2009	All	All	All	MYC
Pontiac	G8	2008-2009	All	All	All	MYC

### **Supersession Statement**

This PI Was Superseded To Update Models And Model Years. Please Discard PIP4021C.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### **Condition/Concern**

Customers may comment that they hear a high pitched tone or whine type noise from the vehicle with the key on and engine off, or for up to one minute after the vehicle has been shut off. The noise should be heard from outside the vehicle only or with a window open.

It will be most noticeable in an enclosed area (i.e. garage, car wash...etc).

### **Recommendation/Instructions**

The whine/tone may be caused by the internal transmission solenoids being commanded to minimum line pressure by the TCM.

This noise should be considered an operating characteristic and no repairs should be attempted.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Online URL:

<https://www.xlr-net.com/knowledgebase/article/2006-2009-cadillac-xlr-and-xlr-v-service-bulletin-pip4021d-high-pitch-whine-or-buzz-noise-heard-from->

[under-the-vehicle-feb-21-2019-142.html](#)