

# 2004 - 2005 Cadillac XLR: Service Bulletin: Erratic Fuel Gauge Readings, Fuel Gauge Reads Empty When There Is Fuel In Tank

**Subject:** Erratic Fuel Gauge Readings, Fuel Gauge Reads Empty When There Is Fuel In Tank, DTC P0463 Set, Service Fuel System Message Displayed

**Number:** 05.06.04.041A

**Models:** 2004-2005 Cadillac XLR  
2003 Chevrolet Corvette (Built After December 2002)  
2004-2005 Chevrolet Corvette Built Prior to December 2004

**Attention:** For the 2003 Chevrolet Corvette, this bulletin only applies to vehicles with the FFS fuel system.

## Condition

Some customers may comment that the fuel gauge is erratic or reads empty when there is fuel in the tank. Also, the driver information center may display "Service Fuel System."

Upon investigation, the technician may find DTC P0463 set.

## Cause

This condition may be due to the following causes:

- The sender card has insufficient ink and loses electrical contact when the tank is over filled.
- Loose or poor connections at the PCM.

## Correction

Check the connections at the PCM/ECM using the proper pin drag test. Use care to select the proper pin for testing. If all connections check good, then replace the left fuel tank level sensor with P/N 88967316.

Right fuel tank senders are rarely faulty and should only be replaced if diagnostic information specifically indicates replacement of the right fuel tank sender or a DTC P2068 is present.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained

technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL: <https://xlr-net.com/knowledgebase/article.php?id=100>