

2004 Cadillac XLR: Recall: Special Coverage Adjustment - Fuel Tank Quick Connector Leak

Some 2004 model year Cadillac XLR and Chevrolet Corvette vehicles may have a fuel tank leak at the quick connectors that are used to link the left and right fuel tanks. The customer may notice a fuel odor while the vehicle is being refueled, driven or after it is parked. If the leak becomes large enough, a small amount of fuel may be observed dripping on the ground. The leak may also result in a diagnostic code being set and the illumination of the Check Engine light on the instrument cluster.

The complete recall notice is attached below:

[insl-pe10015-41488](#)

Online URL: <https://xlr-net.com/knowledgebase/article.php?id=77>