

2007 Cadillac XLR

2007 ENGINE Engine Mechanical - 4.4L - XLR




Fig. 226: Identifying ECT Sensor Wiring Harness
Courtesy of GENERAL MOTORS CORP.

10. Disconnect the engine wiring harness from the engine coolant temperature (ECT) sensor at the rear of the right cylinder head.